

## ■ G-CHECK

### Measuring instrument for mesh tension



## ■ Characteristics

- Safe and simple checking of the mesh tension
- Measuring range between 7 and 50 N/cm
- Standardizes the stretching processes
- Usable for all the commonly available types of mesh (PET, PA, steel)
- Optimal handling
- Big and easily readable scale graduation
- Functions without battery respectively without electric power supply
- Simple functional checking
- Adjustable in virtually no time
- Attractive price
- Including calibration certificate

## ■ Accessories

- Plastic box for G-CHECK and accessories
- Glass plate for ease of adjustment